

icare
TONOVET
Plus

INSTRUCTION **MANUAL**

ENGLISH



TONOMETER

Icare® TONOVET Plus
INSTRUCTION MANUAL TV011-002 EN-1.0
The information in this document is subject to change without prior notice.
In a conflict situation the English version prevails.



This device complies with:
RoHS Directive 2011/65/EU

Copyright © 2016 Icare Finland Oy
Made in Finland



Icare Finland Oy/Tiolat Oy
Äyritie 22, FI-01510 Vantaa, Finland
Tel. +358 9 8775 1150, Fax +358 9 728 6670
www.icarefinland.com, info@icarefinland.com

TABLE OF CONTENTS

Safety instructions	3
Intended use	4
Introduction	4
Package Contents	4
Parts of the tonometer	4
Installing or changing the batteries	5
Turning the tonometer on	5
Loading the probe	5
Probe base light indication	5
Measurement	6
Menu functions	8
MEASURE – Access to measurement	8
HISTORY – Old measurements	8
SOUND – Setting of Tonometer buzzer	8
LIGHT – Setting of Probe base light	8
LANGUAGE – Language setting	8
INFO – Device information	8
Turning the tonometer OFF	8
Error and info messages	9
Measurement flow chart	10
Accessories	11
Technical information	11
Performance data	11
Maintenance	12
Replacing / cleaning the probe base	12
Cleaning the tonometer	12
Returning the Icare tonometer for servicing/ repair	12
Periodic Safety Checks	13
Symbols	13
Electromagnetic declaration	13
Guidance and manufacturer’s declaration	14
Electromagnetic emissions	14
Electromagnetic immunity	14
Recommended separation distances between portable and mobile RF communications equipment and Icare TONOVET Plus tonometer	15
Notes	16

SAFETY INSTRUCTIONS



WARNING

The tonometer must not come into contact with the patient’s eyes, except for the probes, which may do so for a fraction of a second during measurement. Do not push the tonometer into the eye (the tip of the probe should be 4-8mm, or 5/32 - 5/16 inch, from the eye).



WARNING

The tonometer should only be opened by qualified service personnel. It contains no userserviceable parts, apart from the batteries and a probe base. The Icare tonometer requires no routine servicing or calibration other than changing the batteries at least every 12 months and changing or cleaning the probe base. If servicing is necessary, contact qualified service personnel or your local Icare representative.



WARNING

Never immerse the Icare tonometer, spray, pour or spill liquid onto the Icare tonometer, its accessories, connectors, switches or openings in the chassis. Dry any liquid on the surface of the tonometer immediately.



WARNING

Use of any accessories other than those specified in the manufacturer’s documentation, with the exception of items sold by the manufacturer as replacement parts for internal components, may result in increased emissions or decreased immunity of the Icare tonometer.



WARNING

Use of any accessory with the Icare tonometer other than those specified may result in increased emissions or decreased immunity of the Icare tonometer.



WARNING

Use only the original and certified probes made by the manufacturer. The probes are for single-use (one per testing session) only. Use probes taken only from the intact, original packaging. The manufacturer cannot guarantee sterility of the probe once the seal is compromised. Re-sterilization or re-use of the probe could result in incorrect measurement values, in the breakdown of the probe, cross-contamination of bacteria or viruses, and infection of the eye. Re-sterilization or re-use will void all responsibilities and liabilities of the manufacturer concerning the safety and effectiveness of the tonometer.



NOTE

Read this manual carefully, since it contains important information on using and servicing the tonometer.

Retain this manual for future use.

If you do not use the tonometer, it will switch off automatically after 3 minutes.

When you have opened the package, check for any external damage or faults, particularly for damage to the case. If you suspect that there is something wrong with the tonometer, contact the manufacturer or distributor.

Use the tonometer only for measuring intraocular pressure. Any other use is improper and the manufacturer cannot be held liable for any damage arising from improper use, or for the consequences thereof. Use the tonometer only for measuring intraocular pressure of animals.

Never open the casing of the tonometer, except for the battery compartment or to change the probe base.

This manual contains instructions for replacing batteries and changing the probe base.

Never use the tonometer in wet or damp conditions.

The probe base, battery compartment cover, screws, collar and probes are so small that a child or animal could swallow them. Keep the tonometer out of the reach of children or animals.

Do not use the device if it is broken.

Do not use the device near inflammable substances, including inflammable anesthetic agents.

Prior to each measurement, check that a new disposable probe from an intact package is being used.

Be sure that the probe contains the small plastic round tip in front.

Certain microbiological agents (e.g. bacteria) can be transmitted from the measuring support. To avoid this, clean the forehead support after each patient with a disinfectant, e.g. an alcohol solution.

The tonometer conforms to EMC requirements (IEC 60101-1-2), but interference may occur in it if used near (<1m) a device (such as a cellular phone) causing high-intensity electromagnetic emissions. Although the tonometer’s own electromagnetic emissions are well below the levels permitted by the relevant standards, they may cause interference in other, nearby devices, e.g. sensitive sensors.

If the device is not to be used for a long time, we recommend that you remove its AA batteries, since they may leak. Removing the batteries will not affect the subsequent functioning of the tonometer.

Be sure to dispose of the single-use probes properly (e.g. in a container for disposable needles), because they may contain micro-organisms from the patient.

Batteries, packaging materials and probe bases must be disposed of according to local regulations.

No part of the tonometer or probes are made with natural rubber latex.

INTENDED USE

The Icare TONOVET Plus tonometer is used in the intraocular pressure (IOP) measuring in the veterinary medicine. The Icare TONOVET Plus tonometer is intended for veterinary use only.

INTRODUCTION

The Icare TONOVET Plus tonometer is based on a patented, induction-based rebound method, which allows intraocular pressure (IOP) to be measured accurately, rapidly and without anesthetic.

The tonometer uses the rebound method. A small and light single-use probe makes contact with the eye very briefly. The tonometer measures the deceleration of the probe and the rebound time, and calculates the IOP from these parameters.

A measurement sequence includes six measurements. The probe moves to the cornea and back during every measurement. As a result, after the six measurements the tonometer calculates the final IOP and stores it in the tonometer’s memory.

IOP changes due to the effects of pulse, breathing, eye movements, and body position. Because the measurement is made handheld in fractions of a second, six measurements are needed to obtain the final reading.

Icare TONOVET Plus tonometer has settings for dog, cat, rabbit and horse.

PACKAGE CONTENTS

NOTE!
When you have opened the package, check for any external damage or flaws, particularly for damage to the case. If you suspect that there is something wrong with the tonometer, contact the manufacturer or distributor.

- The package contains:
- Icare TONOVET Plus tonometer
 - 4 x AA batteries
 - 100 single use probes in a box
 - aluminum case
 - IOP pad
 - probe base cleaning container
 - probe base collar, narrow
 - probe base cover
 - quick guide
 - screw driver
 - silicone grip
 - spare probe base
 - USB memory stick including instruction manuals (as PDF)
 - warranty card
 - wrist strap

PARTS OF THE TONOMETER

1. Measuring support
2. Probe base
3. Collar
4. Display
5. Measuring support adjusting wheel
6. Navigation buttons
7. Measure button
8. Select button




INSTALLING OR CHANGING THE BATTERIES

Unscrew the battery compartment locking screw with a screwdriver. Remove the battery compartment cover. Place the wrist strap into the wrist strap attachment at the end of the tonometer.

Insert a new set of four AA batteries. Insert the batteries accordance with the picture below, installation order 1 to 4. Do not use rechargeable batteries.

Replace the battery compartment cover and secure it by screwing it in lightly using the screwdriver. Take care not to use excessive force when screwing the cover into place.



TURNING THE TONOMETER ON

Place the wrist strap around your wrist and secure it. The wrist strap protects the tonometer from dropping onto the floor accidentally.

To turn the tonometer on press the Select or Measure button. The following are illustrations of these two alternative ways of starting the tonometer:



Pressing the Select button




Pressing the Measure button

LOADING THE PROBE

Remove the red probe base cover (do not dispose of the cover) and open the probe tube by removing the cap and insert the probe into the probe base as shown in the image.



After loading the probe the tonometer will be ready for measurement when Play-symbol and **active specie setting** appears on the display.



CHANGING THE SETTING FOR DIFFERENT SPECIES

To change the setting for different species press the Select button to access the menu. Press Navigation buttons and select SETTING by pressing the Select button. Toggle the settings by Navigation buttons and select a specie setting by pressing Select button. To measure return to MEASURE by navigation buttons.

PROBE BASE LIGHT INDICATION

The probe base light serves two purposes. First, it helps guide alignment of the probe by showing a red light when the device is in the wrong position (i.e. too much vertical tilt) and a green light when the orientation is correct. Second, it indicates errors (see section Error and Info Messages) in addition to the display during the measurement sequence. When any of these errors occurs, the probe base light flashes red until the **error is cleared by pressing the Measure button**. The probe base light flashes red also when the yellow or red lights are displayed indicating a measurement sequence with high deviation.

MEASUREMENT

- NOTE**
If you do not use the tonometer, it will switch off automatically after 3 minutes.
- NOTE**
No anesthetic is required when performing measurements.
- NOTE**
Avoid excessive restraining, as it may alter the IOP. Patient's head should be held as lightly as possible; be careful not to put pressure on the neck or the eye ball. If a collar is worn; make sure it is not too tight or remove it for the measurement.

STEP 1. Bring the tonometer near the patient's eye.






Correct head and eye position.






Incorrect head and eye position.

STEP 2. The probe should be in a horizontal position. Keep the probe horizontal and pointing perpendicularly to the center of the cornea. The distance from the tip of the probe to the patient's cornea (see picture) should be 4-8 mm (5/32 - 5/16 inch).



If probe base light indication is set OFF green arrows on display will indicate the correct alignment of the tonometer.



If probe base light indication is set OFF red arrows on display will indicate the incorrect alignment of the tonometer.

Incorrect alignment of the tonometer and red probe base light indication.


STEP 3. You may perform the measurement in single or series mode.



Single mode: Press the Measure button lightly to perform the measurement, **taking care not to shake the tonometer.** The tip of the probe should make contact with the central cornea. Six measurements should be made consecutively, green segments will be lit after every successful measurement. After each successful measurement, you will hear a short beep.

Series mode: Keep the Measure button down to obtain the sequence of six measurements, green segments will be lit after every successful measurement.

To obtain the final reading, six measurements are required. **The measurement values displayed before the final result are average values for all previous measurements (1.-5.). Single measurement values are not shown.**



If there is an erroneous measurement, the tonometer will beep twice and display an error message. Press the Measure button to clear the error message. If several erroneous measurements appear, see error messages segment for additional information.

STEP 4. Once the six measurements have been performed, you will hear a long beep. The final IOP will be shown on the display rounded by green (successful) or yellow (some variation) segments. If variation is too big, red segments will be displayed. Yellow Repeat symbol will be displayed in case of external disturbance (eg. EMC) during the measurement.




The displayed result is an **average of four measurements** as the highest and the lowest reading are discarded before the average calculation.







The colors green, yellow and red indication are related to the standard deviation (SD) of the probe's motion parameters of the four remaining measurements. When red segments are displayed; the measurement should be repeated.

NOTE High IOP may cause high fluctuation, which may cause higher standard deviation.

STEP 5. Following the performance of the entire measurement, a new measurement series can be begun by pressing the Measure button. The tonometer will then reactivate the probe and be ready for the next measurement series with the Play symbol on the display. The measurement sequence can be aborted by pressing the Select button. Place the probe base plug back to cover the probe base when the tonometer is not in use.



MENU FUNCTIONS

			Scrolling between the Menu functions starts from the MEASURE display, press either of the Navigation buttons located around the Select button.		
Menu functions are MEASURE, SETTING, HISTORY, SOUND, LIGHT, LANGUAGE and INFO.					
 MEASURE		 MEASURE	MEASURE – Access to measurement Press the Select button to access. If the probe is not loaded the LOAD display appears. Tonometer is ready for measurement when Play-symbol display appears. To exit, press the Select button.		
 SETTING CANINE	 FELINE	 LAPINE	SETTING – Selecting specie Previously selected specie symbol is displayed. To select another specie, press the Select button and scroll throught the settings by pressing either of the Navigation buttons. To accept selection, press the Select button.		
 HISTORY	42 mmHg CANINE	57 mmHg LAPINE	HISTORY – Old measurements Press the Select button to access. Scroll through the old values by pressing either of the Navigation buttons. Value colors green, yellow and red are related to Standard deviation (SD). To exit, press the Select button.		
 SOUND	 SOUND	 SOUND	SOUND – Setting of Tonometer buzzer Green text and symbol is active setting. Press the Select button to access. Select the volume setting by pressing either of the Navigation buttons. To accept selection, press the Select button.		
 LIGHT ON	 ON	 OFF	LIGHT – Setting of Probe base light (positioning guide) Green text and symbol is active setting. Press the Select button to access. Turn the light ON and OFF by pressing either of the Navigation buttons. To accept selection, press the Select button.		
 LANGUAGE ENGLISH	SVENSKA	DEUTSCH	LANGUAGE – Language setting Green text is active setting. Press the Select button to access. Scroll through the language options by pressing either of the Navigation buttons. To accept selection, press the Select button.		
 INFO		SN 1622AP001 SW 1.00A	INFO – Device information Press the Select button to access. Serial number (SN) of the tonometer. Software version (SW) of the tonometer. To exit, press the Select button.		

TURNING THE TONOMETER OFF




Press the Select button until the display shows the End-symbol.



If you do not use the tonometer, it will switch off automatically after 3 minutes.

ERROR AND INFO MESSAGES

The following messages may appear on the display:

MESSAGE	DESCRIPTION	ACTIONS
	Battery charge is low.	Prepare to replace the batteries.
	The batteries are empty.	Turn the tonometer OFF by pressing Select button. Replace the batteries.
	The probe did not move.	Change the probe. The probe may be twisted or otherwise inserted incorrectly. To clear error messages, press the Measure button, after which the measurement can be repeated.
	The probe did not move properly for several times during the measurement sequence.	Remove and clean the probe base or replace it with new one as instructed in Replacing/cleaning the probe base. To clear error messages, press the Measure button, after which the measurement can be repeated.
	The probe did not touch the eye.	Adjust correct measurement distance 4-8 mm (5/32-5/16 inch). The measurement was taken from too far away.
	Too short measurement distance between the probe and the cornea.	Adjust correct measurement distance 4-8 mm (5/32- 5/16 inch). The measurement was taken from too close. To clear error messages, press the Measure button, after which the measurement can be repeated.
	The probe did not move properly. The probe did not make clean contact with the cornea, because the probe hit an eyelid or eyelashes.	Ensure that the eye is open, measure again. To clear error messages, press the Measure button, after which the measurement can be repeated.
	Internal error detected.	Turn the tonometer OFF by pressing Select button. Contact the seller to arrange sending the device for service.

MEASUREMENT FLOW CHART



ACCESSORIES

SKU	PRODUCT DESCRIPTION	WEIGHT	DIMENSIONS
104	Box of 100 probes	89 g	53 x 109 x 36 mm
7217	Probe base collar	4 g	18 x 18 mm
7218	Probe base collar, narrow	1 g	17 x 18 mm
540	Probe base	4 g	7 x 38 mm
543	Probe base cleaning container	3 g	20 x 56 mm
544	Probe base cover	1 g	19 x 11 mm
559	Wrist strap with lock	4 g	10 x 10 x 270 mm
526	Aluminium case	800 g	240 x 280 x 72 mm
7169	Battery cover & screw	6 g	110 x 25 x 12 mm
565	Silicone grip - green	26 g	45 x 35 x 113 mm
624	IOP pad	38 g	50 x 53 x 16 mm
577	USB memory stick (including instruction manuals as PDF)	44 g	98 x 11 x 93 mm
645	Quick guide	19 g	210 x 148 mm
548	Screw driver	15 g	16 x 90 mm

TECHNICAL INFORMATION

Type: TV011
Dimensions: 24 - 29 mm (W) * 35 - 95 mm (H) * 215 mm (L)
Weight: 140 g (without batteries), 230 g (4 x AA batteries)
Power supply: 4 x AA non-rechargeable batteries, 1.5V alkaline LR6

Measurement range: 10 - 60 mmHg
Accuracy: ± 2.5 mmHg (10 - 30 mmHg) and $\pm 10\%$ (>30 - 60 mmHg)
Repeatability (coefficient of variation): < 8 %
Accuracy of display: 1 mmHg
Display unit: Millimeter of mercury (mmHg)
The serial number is on the inside of the battery compartment cover.
There are no electrical connections from the tonometer to the patient.
The device has BF-type electric shock protection.

Operation environment:
Temperature: +10 °C to +35 °C
Relative humidity: 30 % to 90 %
Atmospheric pressure: 800 hPa - 1,060 hPa

Storage environment:
Temperature: -10 °C to +55 °C
Relative humidity: 10 % to 95 %
Atmospheric pressure: 700 hPa - 1,060 hPa

Transport environment:
Temperature: -40 °C to +70 °C
Relative humidity: 10 % to 95 %
Atmospheric pressure: 500 hPa - 1,060 hPa

Mode of operation: continuous

MAINTENANCE

Follow local regulations and recycling instructions regarding the disposal or recycling of the Icare TONOVET tonometer and accessories.



WARNING

The tonometer should only be opened by qualified service personnel. It contains no userserviceable parts, apart from the batteries and a probe base. The Icare TONOVET tonometer requires no routine servicing or calibration other than changing the batteries at least every 12 months and changing or cleaning the probe base. If servicing is necessary, contact your local Icare representative.

REPLACING/CLEANING THE PROBE BASE

During the use some dirt may collect in the probe base, affecting the probe movement. Replace the probe base every 12 months. Clean the probe base every 6 months. Clean or replace the probe base if the error message Clean Change is displayed.

Instructions for replacing the probe base:

- Replace every 12 months.
- Turn off the tonometer.
- Unscrew the probe base collar.
- Remove the probe base by tilting the tonometer downwards and pulling the probe base out of the tonometer.
- Insert a new probe base into the tonometer.
- Screw the collar in, to lock the probe base.

Instructions for cleaning the probe base:

- Clean every 6 months.
- Fill the probe base cleaning container or other clean container with 70-100 % isopropyl alcohol.
- Turn the power off.
- Unscrew the probe base collar.
- Remove the probe base by tilting the tonometer downwards and pulling the probe base out of the tonometer.
- Insert the probe base into the cleaning container and let soak for 5–30 minutes.
- Remove the probe base from alcohol.
- Dry the probe base by blowing clean canned or compressed air into the hole in the probe base. This will additionally remove possible residual dirt.
- Insert the probe base into the tonometer.
- Screw the collar in, to lock the probe base.



CLEANING THE TONOMETER



WARNING

Never immerse the Icare TONOVET tonometer, spray, pour or spill liquid onto the Icare TONOVET tonometer, its accessories, connectors, switches or openings in the chassis. Dry any liquid on the surface of the tonometer immediately.

Icare TONOVET tonometer’s surfaces have been tested and found chemically resistant to the following liquids:

- 70-100 % isopropyl alcohol
- Mild soap solution
- 95 % Pursept solution

Cleaning instructions for surfaces:

- Turn the power off.
- Dampen a soft cloth with one of the liquids mentioned above.
- Lightly wipe the surfaces of the tonometer with the soft cloth.
- Dry the surfaces with a dry soft cloth.

RETURNING THE ICARE TONOVET TONOMETER FOR SERVICING / REPAIR

Contact your local Icare representative for shipping instructions. Unless otherwise instructed by Icare Finland, there is no need to ship accessories along with the tonometer. Use a suitable carton with the appropriate packaging material to protect the device during shipment. Return the device using any shipping method that includes proof of delivery.

PERIODIC SAFETY CHECKS

We recommend that the following checks be performed every 24 months. Equipment inspection for mechanical and functional damage. Inspection of safety labels for legibility.

SYMBOLS



Attention!!! See instructions



See operating instructions for more information



Serial number



Single use only



BF-type device



Lot number



Manufacturing date




Keep dry




Manufacturer




Do not discard this product with other household-type waste. Send to appropriate facility for recovery and recycling. EU WEEE (European Union Directive for Waste of Electronic and Electrical Equipment)



-10°C 55°C




10% 95%



700hPa 1060hPa


Storage environment



-40°C 70°C



10% 95%



500hPa 1060hPa

Transport environment

Temperature limits

Humidity limits

Atmospheric pressure limits

ELECTROMAGNETIC DECLARATION



WARNING

Use of any accessories and cables other than those specified in the manufacturer’s documentation, with the exception of cables sold by the manufacturer as replacement parts for internal components, may result in increased emissions or decreased immunity of the Icare TONOVET Plus tonometer.




WARNING

Use of any accessory or cable with the Icare TONOVET Plus tonometer other than those specified may result in increased emissions or decreased immunity of the Icare TONOVET Plus tonometer.

TV011 is class B equipment and needs special precautions regarding EMC and needs to be installed and put into service according to EMC information provided in Instruction for use manual.

GUIDANCE AND MANUFACTURER’S DECLARATION–ELECTROMAGNETIC EMISSIONS		
Icare TONOVET Plus tonometer (TV011) is intended for use in the electromagnetic environment specified below. The user of the Icare TONOVET Plus tonometer (TV011) should assure that it is used in such an environment.		
RF emissions CISPR 11	Group 1	Icare TONOVET Plus tonometer (TV011) is battery operated and use RF energy only for its internal function. Therefore, its RF emissions are low and are not likely to cause any interference in nearby equipment.
RF emissions CISPR 11	Class B	Icare TONOVET Plus tonometer (TV011) is suitable for use in all establishments, including domestic establishments and those directly connected to public low-voltage power supply network that supplies buildings used for domestic purposes.
Harmonic emissions IEC 61000-3-2	NOT APPLICABLE	
Voltage fluctuations flickering emissions IEC 61000-3-3	NOT APPLICABLE	

GUIDANCE AND MANUFACTURER’S DECLARATION–ELECTROMAGNETIC IMMUNITY			
Icare TONOVET Plus tonometer (TV011) is intended for use in the electromagnetic enviroment specified below. The customers or users of Icare TONOVET Plus tonometer (TV011) should assure that it is used in such enviroment.			
Immunity test	IEC 60601 Test level	Compliance level	Electromagnetic environment-Guidance
Electrostatic discharge (ESD) IEC 61000-4-2	± 6 kV contact ±8 kV air	± 6 kV contact ± 8 kV air	Floors should be wood, concrete or ceramic tile. If floors are covered with synthetic material, the relative humidity should be at least 30 %
Electrical fast Transients/burst IEC 61000-4-4	±2 kV for power supply lines ±1 kV for input/output lines	NOT APPLICABLE	NOT APPLICABLE
Surge IEC 61000-4-5	±1 kV for line(s) to line(s) ±2 kV for line(s) to earth	NOT APPLICABLE	NOT APPLICABLE
Voltage dips, short interruption and voltage variations on power supply lines IEC 61000-4-11	<5 % UT (>95 % dip in UT) for 0,5 cycle 40 % UT (60 % dip in UT) for 5 cycles 70 % UT (30 % dip in UT) for 25 cycles <5 % UT (>95 % dip in UT) for 5 s	NOT APPLICABLE	NOT APPLICABLE
Power frequency (50/60 Hz) magnetic field IEC 61000-4-8	3 A/m	3 A/m	Power frequency magnetic fields should be at levels characteristic of a typical location in a typical commercial or hospital environment.

GUIDANCE AND MANUFACTURER’S DECLARATION – ELECTROMAGNETIC IMMUNITY			
Icare TONOVET Plus tonometer (TV011) is intended for use in the electromagnetic environment specified below. The customer or the user of the Icare TONOVET Plus tonometer (TV011) should assure that it is such an environment.			
Immunity test	IEC 60601 Test level	Compliance level	Electromagnetic environment-Guidance
Radiated RF IEC 61000-4-3	3 V/m 80MHz to 2,5 GHz	3V/m	Portable and mobile RF communications equipment should be used no closer to any part of the Icare TONOVET Plus tonometer (TV011), including cables, than the recommended separation distance calculated from the equation applicable to the frequency of the transmitter. Recommended separation distance $d = 1.2 \sqrt{P}$ $d = 1.2 \sqrt{P}$ 80 MHz to 800 MHz $d = 2.3 \sqrt{P}$ 800 MHz to 2 5 GHz Where P is the maximum output power rating of the transmitter in watts (W) according to the transmitter manufacturer and d is the recommended separation distance in metres (m). Field strengths from fixed RF transmitters, as determined by an electromagnetic site survey ^a should be less than the compliance level in each frequency range ^b . Interference may occur in the vicinity of equipment marked with the following symbol: 
Conducted RF IEC 61000-4-6	3Vrms 150 kHz to 80 MHz	NOT APPLICABLE	

NOTE 1 At 80 MHz and 800 MHz, the higher frequency range applies.
NOTE 2 These guidelines may not apply in all situations. Electromagnetic propagation is affected by absorption and reflection from structures, objects and people.

^a Field strengths from fixed transmitters, such as base stations for radio (cellular/cordless) telephones and land mobile radios, amateur radio, AM and FM radio broadcast and TV broadcast cannot be predicted theoretically with accuracy. To assess the electromagnetic environment due to fixed RF transmitters, an electromagnetic site survey should be considered. If the measured field strength in the location in which the Icare TONOVET Plus tonometer (TV011) is used exceeds the applicable RF compliance level above, the Icare TONOVET Plus tonometer (TV011) should be observed to verify normal operation. If abnormal performance is observed, additional measures may be necessary, such as re-orienting or relocating the Icare TONOVET Plus tonometer (TV011).
^b Over the frequency range 150 kHz to 80 MHz, field strengths should be less than 3V/m.

RECOMMENDED SEPARATION DISTANCES BETWEEN PORTABLE AND MOBILE RF COMMUNICATIONS EQUIPMENT AND ICARE TONOVET PLUS TONOMETER			
Icare TONOVET Plus tonometer (TV011) is intended for use in an electromagnetic environment in which radiated RF-disturbances are controlled. The customer or the user of the Icare TONOVET Plus tonometer (TV011) can help prevent electromagnetic interference by maintaining a minimum distance between portable and mobile RF communications equipment (transmitters) and Icare TONOVET Plus tonometer (TV011) as recommended below, according to the maximum output power of the communications equipment.			
Rated maximum output power of transmitter (W)	Separation distance according to frequency of transmitter, m		
	150 kHz to 80 MHz $d= 1,2 \sqrt{P}$	80 MHz to 800 MHz $d= 1,2 \sqrt{P}$	800 MHz to 2,5 GHz $d= 2,3 \sqrt{P}$
0,01	NOT APPLICABLE	0.12	0.23
0,1	NOT APPLICABLE	0.38	0.73
1	NOT APPLICABLE	1.2	2.3
10	NOT APPLICABLE	3.8	7.2
100	NOT APPLICABLE	12	23
For transmitters rated at a maximum output power not listed above, the recommended separation distance d in metres (m) can be estimated using the equation applicable to the frequency of the transmitter, where P is the maximum output power rating of the transmitter in watts (W) according to the transmitter manufacturer. NOTE 1 At 80 MHz and 800 MHz, the separation distance for the higher frequency range applies. NOTE 2 These guidelines may not apply in all situations. Electromagnetic propagation is affected by absorption and reflection from structures, objects and people.			

NOTES

[illegible]